



ISO EN

<b>d</b>	<b>M8</b>	<b>M8x1</b>	<b>M10</b>	<b>M10x1</b>	<b>M10x1,25</b>	<b>M12</b>
<b>P</b>	1,25	1	1,5	1	1,25	1,75
<b>m (nom.)</b>	5	5	6	6	6	7
<b>s (nom.)</b>	13	13	17/16*	17/16*	17/16*	19/18*
<b>d</b>	<b>M12x1,25</b>	<b>M12x1,5</b>	<b>M14</b>	<b>M14x1,5</b>	<b>M16</b>	<b>M16x1,5</b>
<b>P</b>	1,25	1,5	2	1,5	2	1,5
<b>m (nom.)</b>	7	7	8	8	8	8
<b>s (nom.)</b>	19/18*	19/18*	22/21*	22/21*	24	24
<b>d</b>	<b>M18</b>	<b>M18x1,5</b>	<b>M18x2</b>	<b>M20</b>	<b>M20x1,5</b>	<b>M20x2</b>
<b>P</b>	2,5	1,5	2	2,5	1,5	2
<b>m (nom.)</b>	9	9	9	9	9	9
<b>s (nom.)</b>	27	27	27	30	30	30
<b>d</b>	<b>M22</b>	<b>M22x1,5</b>	<b>M22x2</b>	<b>M24</b>	<b>M24x1,5</b>	<b>M24x2</b>
<b>P</b>	2,5	1,5	2	3	1,5	2
<b>m (nom.)</b>	10	10	10	10	10	10
<b>s (nom.)</b>	32/34*	32/34*	32/34*	36	36	36
<b>d</b>	<b>M27</b>	<b>M27x1,5</b>	<b>M27x2</b>	<b>M30</b>	<b>M30x1,5</b>	<b>M30x2</b>
<b>P</b>	3	1,5	2	3,5	1,5	2
<b>m (nom.)</b>	12	12	12	12	12	12
<b>s (nom.)</b>	41	41	41	46	46	46
<b>d</b>	<b>M33</b>	<b>M33x1,5</b>	<b>M33x2</b>	<b>M36</b>	<b>M36x1,5</b>	<b>M36x2</b>
<b>P</b>	3,5	1,5	2	4	1,5	2
<b>m (nom.)</b>	14	14	14	14	14	14
<b>s (nom.)</b>	50	50	50	55	55	55
<b>d</b>	<b>M36x3</b>	<b>M39x4</b>	<b>M39x1,5</b>	<b>M39x2</b>	<b>M39x3</b>	<b>M42</b>
<b>P</b>	3	4	1,5	2	3	4,5
<b>m (nom.)</b>	14	16	16	16	16	16
<b>s (nom.)</b>	55	60	60	60	60	65
<b>d</b>	<b>M42x1,5</b>	<b>M42x2</b>	<b>M42x3</b>	<b>M45</b>	<b>M45x1,5</b>	<b>M45x2</b>
<b>P</b>	1,5	2	3	4,5	1,5	2
<b>m (nom.)</b>	16	16	16	18	18	18
<b>s (nom.)</b>	65	65	65	70	70	70
<b>d</b>	<b>M45x3</b>	<b>M48x5</b>	<b>M48x1,5</b>	<b>M48x2</b>	<b>M48x3</b>	<b>M52x5</b>
<b>P</b>	3	5	1,5	2	3	5
<b>m (nom.)</b>	18	18	18	18	18	20
<b>s (nom.)</b>	70	75	75	75	75	80
<b>d</b>	<b>M52x1,5</b>	<b>M52x2</b>	<b>M52x3</b>			
<b>P</b>	1,5	2	3			
<b>m (nom.)</b>	20	20	20			
<b>s (nom.)</b>	80	80	80			
<b>5</b>	<b>8</b>	<b>10</b>	<b>A2</b>	<b>A4</b>		

\* Tamaño según norma ISO.